

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

USNRO REGION II
ATLANTA, GEORGIA

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

31 OCT 29 P 1: 04

TELEPHONE: AREA 704
373-4083

October 23, 1981

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station
Docket Nos. 50-369 and 50-370

Reference: RII:GAB
Inspection Report 50-369/81-17 and 50-370/81-05
Violation 50-369/81-17-02

Dear Mr. O'Reilly:


Per request of Mr. G. A. Belisle of your office in a telephone conversation with Duke Power Company on October 14, 1981, the following supplemental information is provided in regard to the subject violation.

A program was instituted in February of 1980 under which all temporary modifications are identified by a unique tag and by stamping the work request used to install them. Since the implementation of this program the site Q.A. group has performed three separate audits on temporary modifications (May 1980, October 1980, and April 1981). These audits included extensive plant tours looking for uncontrolled temporary modifications. None were identified.

Due to the information stated above, it is felt the jumper found during the subject inspection was an isolated case and no further corrective actions are necessary.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge.

Very truly yours,


William O. Parker, Jr.

PBN/php

8111130353 811104
PDR ADOCK 05000369
Q PDR