

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
AR A NO 1 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58																			
REPORT SOURCE L 0 5 0 0 0 3 1 3 7 0 8 2 6 8 1 8 1 0 0 5 8 1 9 DOCKET NUMBER 60 61 EVENT DATE 74 75 REPORT DATE 80																			
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																			
During Cold Shutdown operation, a leak was discovered in the weld of a																			
drain line of the "A" Decay Heat (DH) Pump discharge piping. The leak was																			
between the Decay Heat pipe and drain line valve, DH-1009. The "A" DH																			
pump was secured placing the unit in a Limiting Condition of Operation																			
per T.S. 3.1.1.6. This occurrence is similar to LER's 50-313/76-012,																			
76-024, 76-025, 77-027, & 79-003.																			
Reportable per T.S. 6.12.3.2.D and T.S. 6.12.3.2.B.																			
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SURCODE VALVE SURCODE C F 11 E 12 B 13 P I P E X X 14 A 15 Z 16 LER NO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO 8 1 0 1 3 0 3 L 0 ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM 50H PRIME COMP SUPPLIER COMPONENT MANUFACTURER A 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 Z 9 9 9 9 26																			
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																			
Failure is believed to be a result of vibration fatigue. The cracked weld																			
and associated drain line were cut out, repped and welded back in place.																			
The drain valve was moved closer to the main line and a hanger was added																			
to lessen drain line vibration. The "A" DH Loop was returned to service																			
following repair.																			
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION G 28 0 0 0 29 NA A 31 Operator Tour ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE Z 33 Z 34 NA NA PERSONNEL EXPOSURES PERSONNEL INJURIES LOSS OF OR DAMAGE TO FACILITY PUBLICITY NUMBER TYPE DESCRIPTION NUMBER DESCRIPTION TYPE DESCRIPTION 0 0 0 37 Z 38 NA 0 0 0 40 NA Z 42 NA N 44 NA																			