

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO CAT 50

01 REPORT SOURCE 1 E 0 5 0 0 0 0 3 1 1 7 1 0 0 9 8 1 8 1 1 0 6 8 1 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On October 9, 1981, Individual Rod Position Indicators (IRPI) for rods 2C1 and 2D2,
03 at 1715 and 2109 hours, respectively, were in disagreement with the Control Rod
04 Bank Demand Indicator by greater than + 12 steps. They were declared inoperable
05 and Action Statement 3.1.3.2.1.a was entered.

06

07

08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
R B 11 E 12 E 13 I N S T R U 14 I 15 Z 16

17 LER RD REPORT NUMBER 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO
8 1 1 0 8 1 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED INPRD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
A 1E Z 19 Z 20 Z 21 0 0 0 0 Y 22 Y 24 L 25 B 0 4 0 1

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The operational amplifier in the Rod Position Indicator for IRPI 2C1 was replaced.
11 A hot calibration was performed on IRPI 2D2, using new input data. IRPI 2C1 and
12 2D2 were tested satisfactorily, and at 2100 hours, October 9, and 1000 hours,
13 October 16, 1981, respectively, Action Statement 3.1.3.2.1.a was terminated.
(81-46, 81-47, 81-48, 81-49, 81-61, 81-68, 81-78, 81-80, 81-97, 81-98)

14

15 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
E 26 0 7 6 29 NA A 31 Operator Observation

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
Z 33 Z 34 NA NA

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
0 0 0 37 2 38 NA

18 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
0 0 0 40 NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
Z 42 NA

20 PUBLICITY ISSUED DESCRIPTION (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35
N 44 NA

NAME OF PREPARER

Frank Dickey

PHONE

609-935-5100

8111170251 811106
PDR ADOCK 05000311
PDR

NRC USE ONLY

GPO 91-7-976