


TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37407  
400 Chestnut Street Tower II ATLANTA, GEORGIA

October 16, 1981

81 OCT 20 P12: 50

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 81-02 - RII:JPO 50-518,  
-519, -520, -521, -553, -554 - HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS.

Please reference your letter dated April 9, 1981 to H. G. Parris which transmitted OIE Bulletin 81-02 for TVA action and my first interim response to you dated July 8, 1981. This letter constitutes our final response to the subject bulletin.

We have completed our investigation and have determined that none of the potentially deficient valves identified in the subject bulletin are to be supplied for the Hartsville or Phipps Bend Nuclear Plants. If you have any questions, please call Jim Domer at FTS 857-2014.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

A handwritten signature in cursive script, appearing to read "L. M. Mills".

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Division of Reactor Operations Inspection  
Washington, DC 20555

8111170257 811016  
PDR ADOCK 05000518  
Q PDR

IE11  
3/0