

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401


1750 Chestnut Street Tower II

USNRC REGION II  
ATLANTA, GEORGIA

November 10, 1981

31 NOV 12 A 8:30

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - BOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE  
REPORT SORO-50-327/81125

The enclosed report provides details concerning the inoperability of the auxiliary building gas treatment system because of an initial design error of secondary containment. This event placed the unit in the action statement of limiting condition for operation 3.7.8.1 and 3.0.3 and is reportable under Technical Specification 6.9.1.12.i.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Green*  
J. A. Green  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Records Center

Institute of Nuclear Power Operations  
1820 Water Place  
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

8111170477 811110  
PDR ADOCK 05000327  
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

*TE22*  
*5*  
*11*