

US-RC REGION II
ATLANTA, GEORGIA
TELECOPY

91 NOV 12 AM : 01

November 9, 1981

Mr. J. P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
101 Marietta St., Suite 3100
Atlanta, GA 30303

REGIONAL DIRECTOR
DEPUTY DIRECTOR
ASSISTANT TO DIRECTOR
DIRECTOR, RRPI
DIRECTOR, EPOS
DIRECTOR, ENF/INV
DIRECTOR, ETI
PUBLIC AFFAIRS OFFICER

Re: Docket No. 50-302
Licensee: DPR-72

This will confirm a report to Mr. Howard Wong at the Nuclear Operations Center in Bethesda, Maryland, on November 7, 1981, at 1245.

At 2020 on November 6, 1981, while switching from Decay Heat Removal on "B" Train to "A" Train approximately 800 gallons of water from the Borated Water Storage Tank overflowed the Reactor Coolant System and spilled water on the Reactor Building floor. It was determined that this event is reportable under the Code of Federal Regulations, Title 10, Part 20.403 b.4.

There was no effect upon the health or safety of the general public.

A detailed report will follow within thirty (30) days.

D. C. Poole

D. C. Poole
Nuclear Plant Manager
Florida Power Corporation
Crystal River Unit #3
Crystal River, FL 32629



Sent by telecopy at _____

Verified received by NRC _____ at _____

/rc

8111190492 811109
PDR ADOCK 05000302
S PDR

IF29
51/0