



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

November 6, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Primary Containment Isolation System Relay Failure

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.1.i since it represents a potentially generic problem with relays of this type.

Daniel Musolf for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/bd

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

-over-

8111190719 811106
PDR ADOCK 05000263
S PDR

IE22
NOV 9 1981