



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

November 12, 1981

Director, I&E Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-306 License No. DPR-60

Containment Purge Supply Valves Failed Local Leak Rate Test

The Licensee Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.1.c since it represents degradation of a primary containment penetration leakage barrier.

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/bd

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

8111200414 811112
PDR ADOCK 05000306
S PDR

IE22 511 NOV 16 1981