

TENNESSEE VALLEY AUTHORITY


CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

81 NOV 17 4 3 10

November 11, 1981

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/81004 REVISION 2

The enclosed report is a supplement to my letters to you dated February 3, 1981, and April 27, 1981, concerning diesel generator 3A and diesel breaker 1836 which tripped from diesel generator overspeed during diesel generator emergency load acceptance test. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Loney
H. J. Green

Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

8111200720 811111
PDR ADDCK 05000296
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

IE 22
1/1