

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 N C M G S I 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT									
2 0 1 REPORT SOURCE L 6 0 5 0 0 0 3 6 9 7 1 0 1 6 8 1 8 1 1 1 6 8 1 9 DOCKET NUMBER EVENT DATE REPORT DATE									
3 0 2 While in Mode 4, investigation of a "Loss of Sample Flow" alarm on the unit									
4 0 3 vent airborne radiation monitors EMF's 35, 36, and 37 revealed that the electric									
5 0 4 motor which operates the system's vacuum pump did not rotate, and emitted sparks									
6 0 5 when turned on. The monitors were subsequently declared inoperable per T.S.									
7 0 6 3.3.3.9 which is reportable per T.S.6.9.1.13(b) and similar to previous RO# 81-									
8 0 7 13. Because of the availability of redundant instrumentation, and the periodic									
9 0 8 sampling taken as required by the Tech. Specs., the health and safety of the									
10 0 9 public were unaffected.									
11 0 10 B B 11 E 12 A 13 M O T O R X 14 Z 15 Z 16 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE									
12 0 11 8 1 1 6 7 0 3 L 0 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.									
13 0 12 C 18 Z 19 Z 20 Z 21 0 0 0 0 N 22 N 24 L 25 G 0 6 3 26 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER									
14 0 13 The motor (originally from Unit 2's monitors) that operates the vacuum pump									
15 0 14 was burned-up. The reason for the failure of the motor's electrical windings									
16 0 15 could not be determined. The motor was replaced and the monitors returned to									
17 0 16 service.									
18 0 17 X 28 0 0 0 29 Mode 4 A 31 Alarm DISCOVERY DESCRIPTION 32									
19 0 18 Z 33 Z 34 N/A AMOUNT OF ACTIVITY 35 N/A LOCATION OF RELEASE 36									
20 0 19 0 0 0 37 Z 38 N/A PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39									
21 0 20 0 0 0 40 N/A PERSONNEL INJURIES NUMBER TYPE DESCRIPTION 41									
22 0 21 Z 42 N/A LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43									
23 0 22 N 44 N/A PUBLICITY ISSUED DESCRIPTION 45									
24 0 23 N/A NRC USE ONLY									
25 NAME OF PREPARER Phillip B. Nardoci									