

NO
Supra

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

1	6	0	5	0	0	0	2	7	2	7	0	7	2	2	8	1	8	0	8	2	0	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DUCKET NUMBER

EVEN DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8		SYSTEM CODE I B 11		CAUSE CODE C 12		CAUSE SUBCODE Z 13		COMPONENT CODE Z Z Z Z Z Z 14				COMP SUBCODE Z 15		VALVE SUBCODE Z 16	
0 9															
7 8															
17 LER NO REPORT NUMBER		EVENT YEAR 8 1				SEQUENTIAL REPORT NO 0 7 3		OCCURRENCE CODE /		REPORT TYPE 0 3		REVISION L		NO 0	
ACTION TAKEN X 18 X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER Z 25		COMPONENT MANUFACTURER Z 9 9 9 26	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27															

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

8 9
FACILITY STATUS 30
1 5 E 28
% POWER OTHER STATUS
0 9 5 29 N/A
METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
A 31 Operator noticed channel spiking.
60

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	0 0 0	(37) Z (38)	(39) N/A

7		8		9		11		12	
				LOSS OF OR DAMAGE TO FACILITY				(43)	
				TYPE		DESCRIPTION			
1	9	Z	(42)	N/A					

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45) N/A
2 0 N (44)
7 8 9 10
8112040462 810831
PDR ADOCK 05000272
S PDR
68 69 70
NRC USE ONLY

J. Varga

PHONE

609-935-5100