




Public Service Company of Colorado

16805 Road 19 1/2, Platteville, Colorado 80651-9298

November 23, 1981
Fort St. Vrain
Unit No. 1
P-81291

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012



Reference: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/81-068, Preliminary, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/81-068.

Very truly yours,

Don Warembourg
Don Warembourg
Manager, Nuclear Production

DW/lrb

Enclosure

cc: Director, MIPC

8112040477 811123
PDR ADOCK 05000267
S PDR

IE 22
5/11