

WOLF CREEK

NUCLEAR OPERATING CORPORATION

John A. Bailey
Vice President
Nuclear Operations

April 19, 1990
NO 90-0114

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-137
Washington, D. C. 20555


Subject: Docket No. 50-482: Special Report 90-001 - Steam
Generator Tube Plugging Report

The purpose of this letter is to provide information regarding the number of tubes plugged in each steam generator as required by Wolf Creek Generating Station Technical Specifications (T.S.).

The third steam generator (S/G) inservice inspection, which began March 28, 1990, was completed for S/G's B and D on April 4, 1990. Two tubes in S/G D were mechanically plugged as a result of defects and degradations found during the inspection. These tubes, R50-C66 and R45-C101, were required to be plugged because of defects in excess of 40% as required by T.S. 4.4.5.4.

The complete results of the steam generator tube inservice inspection shall be reported to the Commission in a special report as required by T.S. 4.4.5.5 by April 4, 1991.

Very truly yours,



John A. Bailey
Vice President
Nuclear Operations

BDW/jdl

cc: R. D. Martin (NRC)
D. Persinko (NRC)
D. V. Pickett (NRC)
M. E. Skow (NRC)

2004250110 200419
FDR ADDCK 05000482
S FDC

A047
110