



Commonwealth Edison
Byron Nuclear Station
4450 North German Church Road
Byron, Illinois 61010

May 12, 1990

LTR: BYRON 90-0477
FILE: 3.11.0320

PRIORITY ROUTING

orig+1

FIRST	SECOND
RA	RC
DEA	ETC
DRP	SGA
DRS	HL
DRSS	OL
DRRA	TO
	PAQ

FILE *hus*

Mr. A. Bert Davis
Regional Administrator
Office of Inspection and Enforcement
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, IL 60139

SUBJECT: Commonwealth Edison Steam Generator Eddy Current
Examination During Unit 1 Cycle 3 Refueling Outage

Dear Mr. Davis:

Attached is a report of the Steam Generator Eddy Current Examination performed at Commonwealth Edison, Byron Unit 1 during the Cycle 3 refueling outage of January-February 1990. This report is submitted to you in compliance with the requirements of Mandatory Appendix IV of Section XI of the ASME Boiler and Vessel Code, 1983 Edition through Summer 1983 Addenda.

If there are any additional questions, please contact Mr. J. R. Smith at Byron Station at (815) 234-5441 extension 2847.

Sincerely,

R. Pleniewicz
Station Manager
Byron Nuclear Power Station

RP/JRS/mp

Attachment

cc: T. Maiman/K. Graesser (w/o attachment)
R. Flahive (w/o attachment)
R. Tamminga (w/attachment)
J. Blomgren (w/attachment)
J. Harkness (w/attachment)
J. Hendricks (w/attachment - 2 copies)
T. Schuster (w/attachment)

9006040315 900512
PDR ADOCK 05000454
Q PDC

MAY 29 1990

IE 01