



GPU Nuclear Corporation
Post Office Box 388
Route 9 South
Forked River, New Jersey 08731-0388
609 971-4000
Writer's Direct Dial Number:

February 19, 1993
C321-93-2066

U. S. Nuclear Regulatory Commission
Att: Document Control Desk
Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station
Docket No. 50-219
Additional Information; Response to NRC Bulletin 90-01, Supp. 1
Loss of Fill Oil in Transmitters Manufactured by Rosemount

On December 22, 1992, the USNRC issued Supplement 1 to NRC Bulletin 90-01. On page 12 of that supplement, three reporting requirements relating to Rosemount transmitters were identified. GPU Nuclear responded to that Supplement by letter dated February 10, 1993. On February 18, 1993, the USNRC staff requested one clarification to the original GPUN letter. By this letter, GPU Nuclear provides the requested clarification.

There are no Rosemount model 1153/1154 transmitters manufactured before July 11, 1989 installed in any Safety Related or ATWS applications at the Oyster Creek Nuclear Generating Station. This has been determined by verifying that the serial number of each installed transmitter is greater than 50000.

If any additional information or assistance is required, please contact Mr. John Rogers at 609.971.4893.

John J. Barton
Vice President and Director
Oyster Creek

010134

For

JJB/JJR

cc: Administrator, Region I
Senior Resident Inspector
Oyster Creek NRC Project Manager

9303010343 930219
PDR ADDCK 05000219
G PDR

JE39 1/0