

Duke Power Company
P.O. Box 1006
Charlotte, NC 28201-1006

HAL B. TUCKER
Senior Vice President
Nuclear Generation
(704)382-4531



DUKE POWER

March 5, 1993

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 1
Docket No. 50-369
Inservice Inspection Report, Revision 1
1991 Refueling Outage 7

Attached are revised pages and replacement instructions for Revision 1 to the McGuire Unit 1 Inservice Inspection Report which was sent to you on March 6, 1992. Any questions or comments can be directed to A. J. Hogge at (704) 382-5110.

Very truly yours,

H. B. Tucker

HBT/LTB/lcs

xc: (W/O Attachment)

S. D. Ebnetter
Regional Administrator, Region II

T. A. Reed
ONRR

090031

9303100001 930305
PDR ADOCK 05000369
Q PDR

AOA
11

Subject: McGuire Nuclear Station
Unit 1 1991 Refueling Outage 7
Inservice Inspection Report Revision 1

Please make the following changes / additions to the subject report:

<u>Changes / Additions</u>	<u>Action</u>
NIS-1	Replace
<u>Section 2</u> Pages 1,2,3&4	Replace
<u>Section 3</u> Page 1	Replace
Inservice Inspection Listing RFO 7 Pages 1 thru 89	Replace with Pages 1 thru 87
<u>Section 4</u> Page 1	Replace
Inservice Inspection Results Outage 7 Pages 1 thru 46	Replace
<u>Section 8</u> Page 1	Replace

As required by the Provisions of the ASME Code Rules

- [illegible]

Note: Supplemental sheets in form of lists, sketches, or drawings may be used provided (1) size is 8½ in. x 11 in., (2) information in items 1 through 6 on this data report is included on each sheet, and (3) each sheet is numbered and the number of sheets is recorded at the top of this form.