


James A. Fitzpatrick
Nuclear Power Plant
P.O. Box 41
Lycoming, New York 13093
315 342-3840



Harry P. Salmon, Jr.
Resident Manager

March 3, 1993
JAFF-93-0117

United States Nuclear Regulatory Commission
Document Control Desk
Mail Station P1-137
Washington, D.C. 20555

SUBJECT: DOCKET NO. 50-333
LICENSEE EVENT REPORT: 90-012-02 - Normal and
Emergency Service Water
Corrosion, Silting and
Check Valve Problems

Dear Sir:

This revised Licensee Event Report is submitted to correct the "Event Analysis" for potential inoperability of the control room and relay room cooling function and in accordance with 10CFR50.73 (a)(2)(ii) and (v). The event analysis deficiency in the LER was identified in NRC Inspection Report 50-333/92-81.

Questions concerning this report may be addressed to Mr. Verne Childs at (315) 349-6071.

Very truly yours,

HARRY P. SALMON, JR.

HPS:WVC:tld
Enclosure

cc: USNRC, Region 1
USNRC Resident Manager
INPO Records Center

110009

9303110285 930303
PDR ADDCK 05000333
S PDR

Ent No 1375457008
IE22
11