



Commonwealth Edison
1400 Opus Place
Downers Grove, Illinois 60515

March 9, 1993

Dr. Thomas E. Murley, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 29555

Attn: Document Control Desk

Subject: Braidwood Unit 1
Updated Status of Open Items
NRC Docket No. 50-456

References a) June 7, 1991 A. Hsia letter to T. Kovach
b) April 19, 1991 A. Hsia letter to T. Kovach

Dear Dr. Murley,

On November 3, 1992, Braidwood Unit 1 completed its third refueling outage. Actions regarding the following items were completed during this outage:

NRC TAC# M72114	I.E. Bulletin 88-11 Pressurizer Surge Line Thermal Stratification.
NRC TAC# M74549	Containment Hydrogen Monitoring System Modifications.

NRC acceptance of CECO's actions and schedule regarding these modifications is documented in references a) and b) respectively.

Please address any questions to this office.

Sincerely,

Terrence W. Simpkin
T.W. Simpkin
Nuclear Licensing Administrator

120023

cc: J. Hickman - NRR
B. Clayton - RIII
S. DuPont - Braidwood Senior Resident Inspector

ZNLD/2540/1

9303150059 930309
PDR ADDCK 05000456
F PDR

ADD 1/0