

Georgia Power Company  
40 Inverness Center Parkway  
Post Office Box 1295  
Birmingham, Alabama 35201  
Telephone 205 877-7279

J. T. Beckham, Jr.  
Vice President - Nuclear  
Hatch Project



March 12, 1993

Docket No. 50-366

HL-3186  
004996


U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Edwin I. Hatch Nuclear Plant - Unit 2  
Licensee Event Report  
"As-Found" Primary Containment  
Integrated Leakage Rate Test Failure

Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(v), Georgia Power Company is submitting the enclosed Licensee Event Report (LER) concerning component degradation which resulted in the failure of the "as-found" primary containment integrated leakage rate test. This event occurred at Plant Hatch - Unit 2. This LER was previously submitted with an incorrect LER number. We are resubmitting it to correct the number. No other changes to the LER have been made. The letter supersedes our letter of February 2, 1992 in its entirety.

Sincerely,



J. T. Beckham, Jr.

OCV/cr

Enclosure: LER 50-366/1993-002

cc: Georgia Power Company  
Mr. H. L. Sumner, General Manager - Nuclear Plant  
NORMS

U.S. Nuclear Regulatory Commission, Washington, D.C.  
Mr. K. Jabbour, Licensing Project Manager - Hatch

U.S. Nuclear Regulatory Commission, Region II  
Mr. S. D. Ebnetter, Regional Administrator  
Mr. L. D. Wert, Senior Resident Inspector - Hatch

9303190229 930312  
PDR ADDCK 05000366  
S PDR

