

Duke Power Company
Catawba Nuclear Generation Department
4800 Concord Road
Mek, SC 29745

M.S. TUCKMAN
Vice President
(803)831-3205 Office
(803)831-3426 FAX



DUKE POWER

March 17, 1993

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555

Subject: Catawba Nuclear Station, Unit 2
Docket No. 50-414
End of Cycle 5 Refueling Outage
15 Day Steam Generator Tube Inservice Inspection Report

Pursuant to Catawba Technical Specification 4.4.5.5 a., the following quantities of steam generator tubes were repaired by plugging:

<u>Steam Generator</u>	<u>Number of Tubes Plugged</u>
A	14
B	6
C	13
D	10

For further information, please contact Charles R. Lewis at (803)-831-3076.

Very truly yours,

M. S. Tuckman

CRL/SG15DU2.393

xc: S. D. Ebnetter
Regional Administrator, Region II

R. E. Martin, ONRR

W. T. Orders
Senior Resident Inspector, CNS

9303220201 930317
PDR ADOCK 05000414
G PDR

100

AC47 1/0