



Commonwealth Edison  
LaSalle County Nuclear Station  
2601 N. 21st. Rd.  
Marseilles, Illinois 61341  
Telephone 815/357-6761

March 10, 1993

Mr. A. B. Davis  
Region III Administrator  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Sir:

This Special Report is submitted in accordance with LaSalle Unit 2 Operating License NPF-18, Appendix A, and Technical Specifications 3.7.6 and 6.6.C.

On February 15, 1993 at 1140 hours, the Three Hour Fire Rated Divisional Wall (from columns 16 to 17 and Row L.4) separating Fire Zones 4E2-1 and 4E2-2 at elevation 731' in the Unit 2 Auxiliary Building was inoperable for greater than seven days due to a void at the top of the fire rated assembly. The fire proofing which originally sealed the void was degraded thereby creating the opening at the top of the wall.

This void was identified on February 8, 1993 at 1140 hours while inspecting the Unit 2 Fire Rated Assemblies in accordance with LTS-100-42, Fire Assembly Integrity Inspection.

In accordance with Action Statement "A" of Technical Specification 3.7.6, Fire Detection was verified operable on one side of the inoperable Fire Assembly and an Hourly Fire Watch was established. The Fire Watch remained in place until the void was sealed (per work request No. L21198) and declared operable on February 17, 1993 at 0940 hours.

A Special Report is required because the Fire Rated Assembly was inoperable for greater than seven days.

*G. F. Spedl*  
G. F. Spedl  
Station Manager  
LaSalle County Station

GFS/RV/mk1

cc: Nuclear Licensing Administrator  
INPO - Records Center  
NRC Document Control Desk  
NRC Resident Inspector  
IDNS Resident Inspector

220096

9303230017 930310  
PDR ADOCK 05000374  
S PDR

*DE22 1/0*