



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401-1927  
Telephone (612) 330-5500

March 19, 1993

Report Required by  
10 CFR Part 50, Section 50.73

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

Main Steam Isolation Valves Local Leak Rate Exceeded

The supplemental Licensee Event Report for this occurrence is attached. This report contains the following new NRC commitments:

1. A sample of the film on the MSIV seats was removed and sent for analysis. The results should be received in about two months.
2. Long-term modifications and repairs are being evaluated to address issues related to MSIV design and original manufacture.

Please contact Terry Coss, Sr Licensing Engineer, at (612) 295-1449 if you require further information.

*TEC* for

Thomas M Parker  
Director of Licensing  
Nuclear Generation

c: Regional Administrator - III NRC  
Sr Resident Inspector, NRC  
NRR Project Manager, NRC  
State of Minnesota,  
Attn: Kris Sanda

Attachment

240023

9303240183 930319  
PDR ADOCK 05000263  
P PDR

*TEC*