



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

March 22, 1993

10 CFR Part 50
Section 50.73

US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60


Unit 1 Reactor Trip Due to Inadvertent Relay Operation
Which Caused Loss of No. 12 Reactor Coolant Pump

The Licensee Event Report for this occurrence is attached. In this report, we make the following new NRC commitments:

Several corrective actions designed to prevent recurrence of this event will be evaluated. The corrective actions under evaluation include:

- Further use of physical barriers and exclusion areas around electrical equipment.
- Alternatives to the practice of using power buffers and burnishers in proximity of electrical equipment.
- Changes to the training program to include working around sensitive equipment.

Please contact Gene Eckholt (612) 388-1121 ext 4663 if you have any questions related to the information we have provided.


Thomas M. Parker
Director
Nuclear Licensing

c: Regional Administrator - III, NRC
NRR Project Manager, NRC
Sr Resident Inspector, NRC
State of Minnesota
Attn: Kris Sanda
J E Silberg

Attachment

9303260204 930322
PDR ADOCK 05000282
S PDR

TE22
11