



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

March 22, 1993

U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

10 CFR Part 50
Section 50.90

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Correction to February 12, 1993 License Amendment Request

We have discovered a typographical error that appeared in our February 12, 1993 License Amendment Request titled "Revised Core Spray Pump Flow and Other Editorial Corrections". The error appears on page A-3 of the submittal and concerns the proposed new wording for Specification 3.6.E.1 (Page 127). The proposed wording for the specification, as it appeared on page A-3 of the submittal, was as follows:

"During Operating Conditions and whenever reactor coolant pressure is less than 100 psig and temperature is greater than 345°F..."

The proposed wording was intended to read as follows (underlining added for emphasis):

"During power operating conditions and whenever reactor coolant pressure is greater than 110 psig..."

The error only appeared in the text on page A-3 of the submittal. The proposed wording for the specification was presented correctly in Exhibits B and C of that submittal. We apologize for this error and any confusion it may have caused during your review.

This letter contains no new NRC commitments, nor does it modify any prior commitments.

Please contact Terry Coss at (612) 295-1449 if you require further information related to this request.

Thomas M Parker
Director
Nuclear Licensing

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
State of Minnesota
Attn: Kris Sanda

J Silberg

9303290040 930322
PDR ADOCK 05000263
PDR

290049

A001
1/0