

The Light company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483


March 31, 1993
ST-HL-AE-4396
File No.: T07.03
10CFR50

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 1
Docket No. STN 50-498
Unit 1 Fourth Refueling Outage Inservice
Inspection Summary Report for Repairs and Replacements

Enclosed is the Unit 1 fourth refueling outage (1RE04) Inservice Inspection Summary Report for Repairs and Replacements performed under the ASME Code, Section XI at the South Texas Project Electric Generating Station. This Summary Report includes the period from completion of the third refueling outage (April 4, 1991) to completion of the fourth refueling outage (December 31, 1992). In addition, an addendum to this Summary Report will be submitted by May 15, 1993.

If you should have any questions on this matter, please contact Mr. A. W. Harrison at (512) 972-7298.


S. L. Rosen
Vice President,
Nuclear Engineering

HRP/pla

Attachments: Per Attached Index

RREP\93089001.U2

Project Manager on Behalf of the Participants in the South Texas Project

9304130318 930407
PDR ADOCK 05000498
Q PDR