



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

April 12, 1993

ASME Code Section XI
IWA-6220

Office of Nuclear Reactor Regulation
Attn: Document Control Desk
US Nuclear Regulatory Commission
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-262 License Nos. DPR-42
50-306 DPR-60

Unit 1 Inservice Inspection Summary Report -
Refueling Outage No. 15
Unit 2 Inservice Inspection Summary Report -
Maintenance Outage

Attached for your information are four copies of the report, Prairie Island Nuclear Generating Plant - Unit 1 Inservice Inspection Examination Summary, October 24, 1992 to January 12, 1993, Refueling Outage Number 15, Inspection Period 3, Second Interval and four copies of the report Prairie Island Nuclear Generating Plant - Unit 2 Inservice Inspection Summary Report October 23, 1992 to January 11, 1993, Period 3, Second Interval. Each Inservice Inspection Summary Report includes the ASME Section XI Repair/Replacement Summary report. The first Inservice Inspection Summary Report is a summary of the examinations performed during the last refueling outage of Unit 1 and performed during an unplanned Unit 1 steam generator outage just prior to the refueling outage. The second report is a summary of the examinations performed during the planned Unit 2 maintenance and modification outage which ended January 11, 1993. The ASME Section XI Repair/Replacement Summary Report is a summary of the repairs and replacements to ASME Code Class 1, 2 and 3 components and systems during the last refueling outage of the Prairie Island Nuclear Generating Plant Unit No. 1 and the last maintenance outage of the Prairie Island Nuclear Generating Plant - Unit 2.

The Inservice Inspection Summary reports identify components examined, the examination methods used, the examination number, and summaries of the results. All anomalies were either corrected or an engineering evaluation was performed to accept "as is" conditions. The ASME Section XI Repair/Replacement Summary reports identify work request numbers and summaries of the work.

The Inservice Inspection Summary Reports are being submitted in accordance with the Prairie Island ASME Code Section XI Inservice Inspection and Testing Program. The submittals of the attached summary reports are intended to satisfy the inspection reporting requirements contained in IWA-6220 of the ASME Boiler and Pressure Vessel Code.

9304160118 930412
PDR ADOCK 05000262
G PDR

HOA
11

USNRC
April 12, 1993
Page 2

Northern States Power Company

Please contact us if you have any questions related to the information presented in these reports.



Roger O Anderson
Director
Licensing and Management Issues

c: Regional Administrator-III, NRC (2 copies of attachment)
NRR Project Manager, NRC (1 copy of attachment)
NRC Resident Inspector (w/o attachment)
J Silberg (w/o attachment)
Chief Boiler Inspector, State of MN (1 copy of attachment)
Paul Fisher, Hartford Ins. (1 copy of attachment)

Attachment