



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

April 14, 1993

Report Required by
10 CFR Part 50, Section 50.73

US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Potential Emergency Filter Train System Inoperability
Due to Interaction with Non-Safety Related Equipment

The supplemental Licensee Event Report for this occurrence is attached. This report contains the following new NRC commitments.

1. The "B" Filtration train flow controller for damper VD-9111B has been placed in manual and set at 75%.
2. Administrative Controls have been initiated to maintain the "A" Filtration train in "Lead" with the "B" Filtration train in "Lag".

Please contact Marv Engen, Sr Licensing Engineer, at (612) 295-1291 if you require further information.

Roger O Anderson
Director
Licensing and Management Issues

c: Regional Administrator - III, NRC
NRR Project Manager, NRC
Sr Resident Inspector, NRC
State of Minnesota
Attn: Kris Sanda

Attachment

9304200233 930414
PDR ADOCK 05000263
S PDR

JE22