



Northern States Power Company

April 23, 1993

Mr A Bert Davis
Regional Administrator, Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60

Systematic Assessment of Licensee Performance (SALP)
Inspection Reports No. 50-282/93001 and 50-306/93001

We have had the opportunity to review the Initial SALP 10 Report for Prairie Island Units 1 and 2 covering the period May 1, 1991 through January 31, 1993. We have also had the benefit of reviewing the content of the report with you and other Region III representatives at the April 23 meeting at the Prairie Island site.

We appreciate the high quality feedback the SALP process provides related to the operation of our nuclear generating plants. We find the Initial SALP 10 report to be accurate and fair. The analyses provided in the report will be used to strengthen those areas where weaknesses are evident and provide further improvements in those areas in which we performed strongly.

D D Antony
Vice President
Nuclear Generation

cc: Senior Resident Inspector, NRC
NRR Project Manager, NRC
G Charnoff