



Carolina Power & Light Company

APR 26 1993

SERIAL: NLS-93-094

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-324/LICENSE NO. DPR-62

RESPONSE TO NRC BULLETIN 90-01, SUPPLEMENT 1
LOSS OF FILL OIL IN TRANSMITTERS MANUFACTURED BY ROSEMOUNT

Gentlemen:


The purpose of this letter is to provide Carolina Power & Light Company's (CP&L) notification of work completion at the Brunswick Steam Electric Plant, Unit No. 2 (BSEP2).

In our response to NRC Bulletin 90-01, Supplement 1 for BSEP2, CP&L committed to remove and replace eight (8) Rosemount transmitters to be in compliance with the Bulletin Supplement requirements prior to BSEP2 startup.

The eight (8) Rosemount transmitters have been removed and replaced as of March 16, 1993, as was committed in our response. BSEP2 has therefore complied with item 1 of the Requested Actions for Operating Reactors. This commitment is considered closed.

If further information is needed, please contact Mr. Fred Emerson at (919) 546-7573.

Yours very truly,


for David C. McCarthy
Manager
Nuclear Licensing Section

JHH/jbw

cc: Mr. S. D. Ebnetter
Mr. P. D. Milano
Mr. R. L. Prevatte

300084

411 Fayetteville Street * P. O. Box 1551 * Raleigh, N. C. 27602

9305030030 930426
PDR ADOCK 05000324
Q PDR

JE391/0
(1974GLU)