



**CENTERIOR  
ENERGY**

Donald C. Shelton  
Vice President - Nuclear  
Davis-Besse

300 Madison Avenue  
Toledo, OH 43652-0001  
(419) 249-2300

Docket Number 50-346

License Number NPF-3

Serial Number 2145

May 12, 1993

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Subject: Completion of Upgrade to Fire Detection Zone 410

Gentlemen:

On December 6, 1991, Toledo Edison (TE) submitted a Special Report (NP-40-91-03) to the Nuclear Regulatory Commission (NRC) pursuant to the Davis-Besse Nuclear Power Station (DBNPS) Operating License Appendix A Technical Specifications, reporting the inoperability of Fire Detection Zone (FDZ) 410 (containment building east passage). The letter noted that due to high radiation levels in FDZ 410 during plant operation, this zone would remain inoperable until the eighth refueling outage (8RFO) or an outage of sufficient duration. It was further stated that a supplemental report would be submitted describing the actions taken, once FDZ 410 was returned to an operable status. This letter satisfies that commitment.

On May 19, 1992, TE submitted a revision to the above mentioned Special Report, stating TE's plans to upgrade the FDZ 410 fire detectors with new state-of-the-art detectors during 8RFO. This upgrade was accomplished during the 8RFO and FDZ 410 was returned to an operable status.

170124

9305180294 930512  
PDR ADDCK 05000346  
P PDR

Operating Companies:  
Cleveland Electric Illuminating  
Toledo Edison

A006  
1/0

Docket Number 50-346  
License Number NPF-3  
Serial Number 2145  
Page 2

If you have any questions regarding this matter, please contact  
Mr. Robert W. Schrauder, Manager - Nuclear Licensing, at  
(419) 249-2366.

Very truly yours,



MKL/dlc

cc: A. B. Davis, Regional Administrator, NRC Region III  
J. B. Hopkins, NRC Senior Project Manager  
S. Stasek, DB-1 NRC Senior Resident Inspector  
J. R. Williams, Chief of Staff, Ohio Emergency Management Agency,  
State of Ohio (NRC Liaison)  
Utility Radiological Safety Board