

TELECOPY

15 December 1980

Director
Deputy Director
Ass't to Director
Admin. Officer
RONS Chief
RCES Chief
PFMS Chief
Sfgds Chief
PA Officer

Mr. J. P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
191 Marietta St., Suite 3100
Atlanta, GA 30303

Bl. Gibson
S. Perkins

RE: Bucket 50-302
Licensee: DPR-72

THIS WILL CONFIRM A REPORT TO C. A. JULIAN OF YOUR OFFICE AT
1325 ON MONDAY, DECEMBER 15, 1980.

WHILE INVESTIGATING THE SOURCE OF LEAKAGE IN THE SOUTHWEST CORNER
OF THE PLANT DRY, FIRE SERVICE VALVE FSY-107 WAS CLOSED FOR AP-
PROXIMATELY TWO (2) HOURS. THE DELUGE SYSTEM WAS ISOLATED AND A
CONTINUOUS FIRE WATCH WAS NOT ESTABLISHED WITHIN ONE (1) HOUR.
THE FIRE HOSE STATIONS IN THE AUXILIARY BUILDING DID NOT HAVE AN
EQUIVALENT CAPACITY FIRE HOSE ROUTED TO THEM. THIS CREATED AN
EVENT REPORTABLE UNDER TECHNICAL SPECIFICATION 6.9.1.8.b.

THERE WAS NO EFFECT UPON THE GENERAL PUBLIC AS A RESULT OF THIS
EVENT.

A DETAILED REPORT OF THIS EVENT WILL FOLLOW WITHIN FOURTEEN (14)
DAYS.

clerk

D. C. POOLE
NUCLEAR PLANT MANAGER
FLORIDA POWER CORPORATION
CRYSTAL RIVER, FLORIDA

/rc



3108060818

S