



ARKANSAS POWER & LIGHT COMPANY

Arkansas Nuclear One  
P.O. Box 608  
Russellville, Ark.  
Apr. 5, 1982

ANO-82-2441

Mr. John Collins  
Regional Administrator  
Office of Inspection & Enforcement  
Region IV  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Subject: LER 50-313/82-009

Dear Mr. Collins:

This letter confirms the telephone conversation between Mr. William D. Johnson (ANO Resident NRC Inspector) and Mr. James P. O'Hanlon (ANO General Manager) at 1730 hours on April 2, 1982. This item is reported in accordance with ANO-1 Technical Specifications 6.12.3.1(i).

At approximately 1430 hours on April 2, 1982, the determination was made that at least two of the High Pressure Injection Nozzles on the ANO Unit-1 Reactor Coolant System would require corrective action. The unit was in cold shutdown at the time of this determination. Corrective action will be performed on these nozzles before returning to power operation.

Further details will follow in Licensee Event Report (LER) 50-313/82-009/01T-0.

Sincerely yours,

James P. O'Hanlon  
General Manager  
Arkansas Nuclear One

JPO:clc

cc: W. Cavanaugh, III  
J.M. Griffin  
J.R. Marshall  
INPO  
Resident NRC Inspectors  
ANO-DCC

IF-229  
1/0

8204130177 820405  
PDR ADDCK 05000313  
S PDR