




**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 2, 1982

G. D. McLENDON
Senior Vice President
W3K82-0200
Q-3-A35.07.32

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Interim Report of Significant Construction Deficiency No. 32
"Stress Analysis for Welded Pipe Support Attachments Was Not
Performed Prior to Fabrication"

Reference: LP&L Letter W3K81-0286 to USNRC dated August 10, 1981

Dear Mr. Collins:

In the referenced letter LP&L committed to submitting a final report on
Significant Construction Deficiency No. 32 on or before April 1, 1982.

Ebasco has informed LP&L that additional time is required in order to
complete the corrective action and documentation review on this Significant
Construction Deficiency. At this time, construction has completed 85
percent of the corrective action on this Significant Construction
Deficiency.

The date established for the submittal of a final report is now October 15,
1982.

If there are any questions, please let us know.

Very truly yours,

G. D. McLendon

GDMcL/LLB/rd

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-27

S110

8204130359 820402
PDR ADOCK 05000382
S PDR