

**LICENSEE EVENT REPORT**

EXHIBIT A

CONTROL BLOCK: 1										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																																																																					
0	1	S	C	N	E	E	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5																																																			
LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE										CAT 56																																																	
CON'T										REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE																																							
0	1	I	S	0	5	0	0	0	2	6	9	7	0	3	0	6	8	2	8	0	4	1	6	8	2	9																																																					
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10																																																																															
On March 6, 1982, a steam generator tube leak of approximately 0.08 GPM was																																																																															
indicated by the Condensate Steam Air Ejector Offgas Radiation Monitor. This																																																																															
constitutes an abnormal degradation of the reactor coolant pressure boundary and																																																																															
is reportable pursuant to Technical Specification 6.6.2.1.a(3). Personnel and																																																																															
systems adequately controlled this event and the releases were well within reg-																																																																															
ulatory requirements; thus, the health and safety of the public were not affected																																																																															
by this event.																																																																															
SYSTEM CODE										CAUSE CODE										CAUSE SUBCODE										COMP. SUBCODE										VALVE SUBCODE																																							
0	9	C	B	11	E	12	B	13	H	T	E	X	C	H	14	F	15	Z	16																																																												
EVENT YEAR										SEQUENTIAL REPORT NO.										OCCURRENCE CODE										REPORT TYPE										REVISION NO.																																							
82										006										01										T										0																																							
ACTION TAKEN										EFFECT ON PLANT										SHUTDOWN METHOD										HOURS										ATTACHMENT SUBMITTED										NPRO-4 FORM SUB.										PRIME COMP. SUPPLIER										COMPONENT MANUFACTURER									
B18Z19										A20										A21										0436										Y23										N24										N25										B01526									
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27																																																																															
The apparent cause of the steam generator tube leak was a crack on Tube 78-2.																																																																															
This unit was shut down and cooled down. The leaking tube was stabilized from																																																																															
the top and was explosively plugged from the bottom. Eddy current testing in																																																																															
the lane region showed no tubes unacceptably degraded.																																																																															
FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION																																							
E28										10029										NA										A31										Operator Observation																																							
ACTIVITY CONTENT										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																																																											
M33M34										3.109C										Vent stack to atmos; TB to Keowee tailrace																																																											
PERSONNEL EXPOSURES										DESCRIPTION																																																																					
13737										E38										Maintenance Personnel - 15.145																																																											
PERSONNEL INJURIES										DESCRIPTION																																																																					
00040										NA																																																																					
LOSS OF OR DAMAGE TO FACILITY										DESCRIPTION																																																																					
Z42										NA																																																																					
PUBLICITY										DESCRIPTION																																																																					
N44										NA																																																																					
ISSUED																																																																															
20																																																																															

NAME OF PREPARER J. F. Kutzer

PHONE: 704-373-7139

8204 28 0035