

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

32 APR 14 4:30

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

April 2, 1982

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: Oconee Nuclear Station
Docket No. 50-269



Dear Mr. O'Reilly:

On March 6, 1982, your office was informed that the 1B steam generator had an indicated tube leak of 0.08 gal/min. This constitutes an abnormal degradation of the reactor coolant pressure boundary. Reportable Occurrence Report RO-269/82-06 providing details of this incident was to have been submitted to you by March 19, 1982, pursuant to Technical Specification 6.6.2.1.a(3). On March 19, 1982 a delay was requested until April 2, 1982 to allow additional time to investigate this incident. This investigation is still underway, but will be completed and the report submitted to you no later than April 16, 1982.

Very truly yours,


William O. Parker, Jr.

JFN/php

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
Oconee Nuclear Station

Mr. Philip C. Wagner
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

Tea
5
/0

8204280324