

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

April 8, 1982

32 APR 16 A 8.29
TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369



Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-24 was to have been submitted by April 1, 1982. This 30 day reportable occurrence (per T.S.6.9.1.13) concerns T.S.3.4.1.4, "Two residual heat removal (RHR) loops shall be operable and at least one RHR loop shall be in operation", which was violated on March 2, 1982. At this time, our investigation of the incident is not yet complete. The report will be submitted by April 19, 1982.

Very truly yours,

William O. Parker, Jr.

PBN/jfw

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector-NRC
McGuire Nuclear Station

OFFICIAL COPY

8204280464

TE.22
1/0