

DUKE POWER COMPANY

POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

February 19, 1982

02 FEB 25 P 1: 50

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: Oconee Nuclear Station
Docket No. 50-270



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-270/81-18, Revision 1, which contains a correction to the "Apparent Cause of the Occurrence" and "Corrective Action" as reported in the original submittal. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.a(2), which concerns an operation subject to a limiting condition for operation which was less conservative than the least conservative aspect of the limiting condition for operation established in the Technical Specifications, and describes an incident which is considered to be of no significance with respect to its effect on the health and safety of the public.

Very truly yours,


William O. Parker, Jr.

JFK/php
Attachment

cc: Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
Oconee Nuclear Station

OFFICIAL COPY

8204280536

TE 22