



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

April 21, 1982

Regional Administrator  
Region III  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137



PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-282 License No. DPR-42

Missed Samples of No. 11 Boric Acid Tank

The Licensee Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.(c), since it indicates an observed inadequacy in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

*L O Mayer for*

L O Mayer, PE  
Manager of Nuclear Support Services

LOM/KNC/js

cc: NRC Document Control Desk (1)  
NRC Resident Inspector  
MPCA  
Attn: J W Ferman

8204300240

*IE22  
5/1*

APR 26 1982