

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	7	2	7	0	4	0	5	8	2	8	0	4	2	1	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

0 2 | On April 5, 1982, the Control Room Operator noticed that the indication for No. 12

0 3 | Steam Generator Steam Flow Channel 2 had failed high. The channel was declared

0 4 | inoperable, and at 0655 hours, Limiting Condition for Operation 3.3.2.1 Action 14

0 5 | was entered.

0	6	
---	---	--

07 | _____

08 _____

7 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 11 12 13 14 15 16

9 10 11 12 13 14 15 16 17 18 19 20

17 LER-RO REPORT NUMBER 8 2 —

EVENT YEAR —

SEQUENTIAL REPORT NO. 0 2 1 /

OCCURRENCE CODE 0 3

REPORT TYPE L

REVISION NO. — 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		PRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
E	18	Z	19	Z	20	Z	21	0	0	0	0	22	Y	23	N	24	N	25	Z	Z	Z	Z
32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The high steam flow indication was due to leakage from a loose tubing fitting on

the flow transmitter. The loose fitting was tightened and the leakage stopped.

The transmitter was filled, satisfactorily tested and returned to vice. No. 12

Steam Generator Channel 2 Steam Flow Indication was declared operable at 1031 hours.

April 5, 1982, and Limiting Condition for Operation 3.3.2.1 Action 14 was terminated

7 8 9

FACILITY STATUS (1) 5 (28) G

% POWER (29) 0 0 0

OTHER STATUS (30) N/A

METHOD OF DISCOVERY (31) A

DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE

1	6	2	33	3	34
---	---	---	----	---	----

AMOUNT OF ACTIVITY (35)

N/A

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0 0 0	(37) 2 (38)	(39) N/A					

PERSONNEL INJURIES				DESCRIPTION (41)
1	2	3	4	
0	0	0	(40)	N/A

7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 0 2 (42) N/A
8205040121

7	8	9	10	N/A		8
---	---	---	----	-----	--	---

ISSUED		PUBLICATION	DESCRIPTION	NRC USE ONLY
2	0	N	(44) N/A	

NAME OF PREPARER R. Frahm

PHONE: 609-935-0998