

50.55(e) Report  
RECEIVED  
NRC

ARIZONA



PUBLIC SERVICE COMPANY

P. O. BOX 21666 • PHOENIX, ARIZONA 85036

REGION V

April 5, 1982

ANPP-20613-GHD/BSK

U. S. Nuclear Regulatory Commission  
Region V  
Creekside Oaks Office Park  
1450 Maria Lane - Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. B. H. Faulkenberry, Chief  
Reactor Construction and  
Engineering Support Branch

Subject: Interim Report - DER 82-5  
A 50.55(e) Potentially Reportable Deficiency Relating to  
Unit 2 Reactor Coolant Pump Delivered With Sand In Cooler  
Chamber Housing  
File: 82-019-026  
D.4.33.2

Reference: Telephone Conversation between J. Berdoin and J. Cook on  
March 3, 1982

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the referenced telephone conversation. At that time, it was estimated that a determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim Report is attached. It is now expected that this information will be finalized by July 15, 1982, at which time a complete report will be submitted.

Very truly yours,

E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Projects  
ANPP Project Director

EEVB Jr/GHD:skc

Attachment

cc: See Attached Page 2

8205040222



1E27  
1/6  
82-84

U. S. Nuclear Regulatory Commission  
Attention: Mr. B. H. Faulkenberry, Chief  
April 5, 1982  
ANPP-20613-GHD/BSK  
Page 2

cc: Richard DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

J. A. Roedel  
D. B. Fasnacht  
G. C. Andognini  
A. C. Rogers  
B. S. Kaplan  
W. E. Ide  
J. Vorees  
J. A. Brand  
A. C. Gehr  
W. J. Stubblefield  
W. G. Bingham  
R. L. Patterson  
R. W. Welcher  
R. M. Grant  
D. R. Hawkinson  
L. E. Vorderbrueggen

R. L. Greenfield  
Assistant Attorney General  
Bataan Memorial Building  
Santa Fe, New Mexico 87503

Ms. Patricia Lee Hourihan  
6413 South 26th Street  
Phoenix, Arizona 85040

INTERIM REPORT - DER 82-5  
POTENTIAL REPORTABLE DEFICIENCY  
ARIZONA PUBLIC SERVICE COMPANY (APS)  
PVNGS UNIT 2

I. Potential Problem

Unit 2 Reactor Coolant Pump 1B supplied by Combustion Engineering was delivered to the jobsite with foreign matter in the cooler chamber housing. Two handfuls of material which appears to be blasting sand saturated with oil was in the scupper near the overflow nozzle. This material could have been introduced into the pump lubrication system if not advertently found during Bechtel's work on the pump at the jobsite.

II. Approach To and Status Of Proposed Resolution

Bechtel has requested assistance from Combustion Engineering in evaluating and dispositioning this item.

III. Projected Completion of Corrective Action and Submittal of the Final Report

Evaluation of this condition and submittal of the Final Report is forecast to be completed by July 15, 1982.