



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

April 23, 1982

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Failure of Drywell Vent Isolation Valves

The Licensee Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.1.i since it represents a failure to close of both drywell vent valves.

Dain Musolf FOR
L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/bd

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

8205040484 820423
PDR ADOCK 05000263
S PDR

IE22
5
11
APR 28 1982