



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 30, 1982

G. D. McLENDON
Senior Vice President

W3K-82-0254
Q-3-A35.07.34

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 34
Second Interim Report
"Buffalo Forge HVAC Fan Shrouds"

Reference: 1) LP&L Letter W3K-81-0285 to USNRC dated August 10, 1981
2) Telecon - L. L. Bass (LP&L) to L. Martin (USNRC) on April 29, 1982

Dear Mr. Collins:

LP&L committed to submit a report on the subject SCD by April 30, 1982.
This report will not be submitted until June 25, 1982.

The material to be used to correct the problem is scheduled to be shipped
from Buffalo Forge, Buffalo, New York, to the Waterford 3 site on April 30,
1982. Upon receipt of this material, the corrective action will be performed.


If you have any questions, please let us know.

Very truly yours,

G. D. McLendon

GDMcL/LLB/grf

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



8205070237 820430
PDR ADOCK 05000382
S PDR