

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

R. H. LEASBURG
VICE PRESIDENT
NUCLEAR OPERATIONS

May 5, 1982

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
Attn: Mr. Robert A. Clark, Chief
Operating Reactors Branch No. 3
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Serial No. 267
NO/RMT:acm
Docket No. 50-339
License No. NPF-7

Gentlemen:

NORTH ANNA UNIT TWO
STEAM GENERATOR INSERVICE INSPECTION
SPECIAL REPORT

Enclosed are the results of the first inservice eddy current examination of steam generators conducted during the current refueling outage as requested by your staff. The North Anna Station Nuclear Safety and Operating Committee (SNSOC) reviewed this report and determined that the minor denting raises no safety concerns and continued operation is justified.

This report is not being submitted pursuant to North Anna Power Station Technical Specifications as the results are not above the minimum required for reportability.

Very truly yours,

R. H. Leasburg
R. H. Leasburg

Enclosure

cc: Mr. James P. O'Reilly
Regional Administrator
Region II



8205070259 820505
PDR ADOCK 05000339 PDR
Q

A047
5/11