



**LOUISIANA
POWER & LIGHT**


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 30, 1982

G. D. McLendon
Senior Vice President

W3K82-0257
Q-3-A35.07.49

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 49
Second Interim Report
"Time-Trol, Inc., Heat Trace Panel Malfunctions"

Reference: 1) LP&L Letter W3K82-0210 to USNRC dated April 8, 1982
2) Telecon - L. L. Bass (LP&L) to L. Martin (USNRC) on
April 29, 1982

Dear Mr. Collins:

LP&L committed to submit a report on the subject SCD by April 30, 1982. A report will be submitted to the NRC by June 30, 1982.

At the present time, Ebasco is awaiting Raychem Corp.'s disposition to Nonconformance Report W3-3548. It is anticipated that this response will be received in early May and corrective action will immediately follow.

If you have any questions, please let us know.

Very truly yours,

G. D. McLendon

GDMcL/LLB/ncd

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



8205070381 820430
PDR ADDCK 05000382
S PDR

*FE 27
S/0*