



ARKANSAS POWER & LIGHT COMPANY



Arkansas Nuclear One
P.O. Box 608
Russellville, AR 72801

May 3, 1982

ANO-82-3363

Mr. John Collins
Regional Administrator
Office of Inspection & Enforcement
Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

SUBJECT: Arkansas Nuclear One - Unit 2
Reportable Occurrence 50-368/82-013/01T-0



Gentlemen:

At 11:05 on May 3, 1982, it was noted that ANO-2 battery 2D12 had a cell with voltage less than the required 2.15 V.D.C. It was further noted that out-of-specification readings (2.146 V.D.C. minimum on cell number forty) had been recorded on May 1, 1982, May 2, 1982, and May 3, 1982, and no immediate corrective action applied as required by the "action" requirements of Tech. Spec. 3.8.2.3.b. As a result, the most limiting aspect of the Tech. Spec. action requirement was exceeded, requiring reporting pursuant to Tech. Spec. 6.9.1.8.b.

Tech. Spec. 3.0.3 was applied upon discovery of the lack of corrective action. Immediate action to restore the battery to OPERABLE status was initiated. The battery was restored to OPERABLE status at 11:23, on May 3, 1982, complying with the "action" requirements of Tech. Spec. 3.0.3.

Investigation as to proper long-term corrective action is continuing.

Further details will follow in Licensee Event Report (LER) 50-368/82-013/01T-0.

Sincerely,

James M. Levine
James M. Levine
General Manager

11-29
5/29
/0

JML: BAB:man

cc: W. Cavanaugh, III
J. M. Griffin
J. R. Marshall
INPO
Resident NRC Inspectors
ANO-DCC

8205110216 820503
PDR ADOCK 05000368
S PDR

MEMBER MIDDLE SOUTH UTILITIES SYSTEM