

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J O C P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 66

CON'T 01 L 6 0 5 0 0 0 2 1 9 7 0 4 1 6 8 2 8 0 5 0 3 8 2 9

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Containment oxygen concentration was not reduced to less than 5 percent

03 within 24 hours after placing the reactor mode switch in RUN as required

04 by T.S. 3.5.A.6 and the drywell to torus differential pressure was not

05 greater than 1 psi as required by T.S. 3.5.A.9A. Containment inerting was

06 in progress at the time but had previously lost 6 hours inerting time. A

07 reactor shutdown was commenced while inerting continued. The shutdown

08 was terminated when the T.S. requirement levels were obtained.

09 S E 11 E 12 E 13 I N S T R U 14 E 15 Z 16

SYSTEM CODE 10 11 CAUSE CODE 12 CAUSE SUBCODE 13 COMPONENT CODE 18 COMP SUBCODE 19 VALVE SUBCODE 20

17 8 2 0 2 1 0 1 T 0

LER/RO REPORT NUMBER 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 28 29 REPORT TYPE 30 REVISION NO. 32

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 ATTACHMENT SUBMITTED 41 NPRO-4 FORM 504 42 PRIME COMP SUPPLIER 43 COMPONENT MANUFACTURER 44

E 18 X 19 B 20 Z 21 0 0 0 2 Y 23 Y 24 A 25 L 1 3 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The major cause of the occurrence is the loss of over 6 hours inerting time

11 due to insufficient nitrogen supply and a blown rupture disc in the nitrogen

12 purge line. Engineering to upgrade oxygen analyzer systems and to verify

13 capacity of nitrogen evaporator. At present, reactor will not be put in RUN

14 mode until inerting is completed, unless authorized by the Plant Operations

15 Director.

FACILITY STATUS 1 C 28 0 7 2 29 OTHER STATUS 30 NA METHOD OF DISCOVERY 31 A DISCOVERY DESCRIPTION 32 Operational Event

ACTIVITY CONTENT 1 Z 33 Z 34 AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA

PERSONNEL EXPOSURES 1 0 0 0 37 Z 38 DESCRIPTION 39 NA

PERSONNEL INJURIES 1 0 0 0 40 DESCRIPTION 41 NA

LOSS OF OR DAMAGE TO FACILITY 1 Z 42 DESCRIPTION 43 NA

PUBLICITY 2 N 44 DESCRIPTION 45 NA

ISSUED 2 N 44 DESCRIPTION 45 NA

NAME OF PREPARER Carl Hager PHONE (609) 693-6041