



Consumers
Power
Company

James W Cook

Vice President - Projects, Engineering
and Construction

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0453

April 30, 1982

Harold R Denton, Director
Office of Nuclear Reactor Regulation
Division of Licensing
US Nuclear Regulatory Commission
Washington, DC 20555



MIDLAND PROJECT

MIDLAND DOCKET NO 50-329, 50-330

UNRESOLVED SAFETY ISSUES

FILE: 0505.8 SERIAL: 16876

REFERENCE: CP CO (J W COOK) LETTER DATED FEBRUARY 22, 1982, SERIAL 15993

The reference provided a response to NRC Question 400.9 concerning unresolved safety issues. It has come to our attention that a portion of Issue A-43, Containment Emergency Sump Performance contains a typographical error. On Page 2, Line 11 of A-43, the response states that the highest approach velocity in the vicinity of the containment sump is 0.5 fps. The correct highest approach velocity is 0.2 fps. Please make corrections accordingly.

James W. Cook

JWC/JNL/dsb

CC RJCook, Midland Resident Inspector
RHernan, NRC
RWHuston, Washington
DBMiller, Midland

Boo!
s
1/0

oc0482-0080a100

8205120164 820430
PDR ADDCK 05000329
A PDR