

Mr. R. C. Haynes, Director
Office of Inspection & Enforcement, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

No. 3-82-04/13L-0

Dear Mr. Haynes:

This LER concerns failure of room coolers to start during surveillance test of Core Spray and RHR systems. Governing Tech Spec is 3.5.H.

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A P B S 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CONT
01 REPORT SOURCE L 6 0 5 0 - 0 2 7 8 7 0 4 1 0 8 2 8 0 5 0 5 8 2 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 While performing surveillance tests on the D core spray and
03 D RHR Pumps, the room cooler fans failed to start with the control
04 switches in the auto or run position. The fans were placed into
05 continuous service until the auto and run positions could be
06 verified operable. The pumps were considered operable with the fans
07 operating continuously. Applicable Tech Spec is 3.5.H.
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
S F 11 A 12 C 13 C K T B R K 14 A 15 Z 16
7 8 9 10 11 12 13 14 15 16

17 LER NO REPORT NUMBER 8 2 21 22
18 ACTION TAKEN X 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0 0 0 0 23
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 Investigation revealed that a control circuit had been inadvertently
11 de-energized. The circuit was re-energized and surveillance
12 tests were successfully completed.
13
14

15 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS U/2 Refuel 30 METHOD OF DISCOVERY B 31
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 ACTIVITY RELEASED OF RELEASE 7 33 7 34 N/A 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE N/A 37
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE 2 38 DESCRIPTION N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES NUMBER 0 40 DESCRIPTION N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY TYPE 7 42 DESCRIPTION N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED N 44 DESCRIPTION 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER M. J. Cocroft PHONE (215) 841-5020

8205140400 820505
PDR ADOCK 05000278
S PDR

RECEIVED
MAY 13 1982
U.S. NUCLEAR REGULATORY COMMISSION
DOCUMENT MANAGEMENT DIVISION

IER 50/1

NRC USE ONLY

GPO 51-1-215