

# LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 52

CON'T  
0 1 REPORT SOURCE L 0 5 0 0 0 3 1 6 7 0 4 1 2 8 2 3 0 5 0 6 8 2 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING NORMAL OPERATION, THE WEST CENTRIFUGAL CHARGING PUMP WAS REMOVED FROM  
0 3 SERVICE TO REPAIR A STICKING CHECK VALVE IN THE DISCHARGE LINE OF THE AUXILIARY  
0 4 OIL PUMP. THE CHARGING PUMP WAS UNAVAILABLE PER T.S. 3.1.2.4 FOR FIVE HOURS  
0 5 AND 58 MINUTES. THE EAST CHARGING PUMP WAS AVAILABLE. THE ACTION REQUIREMENTS  
0 6 WERE MET. THIS WAS THE FIRST OCCURRENCE OF THIS TYPE.  
0 7  
0 8  
0 9

0 9 SYSTEM CODE P C 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP SUBCODE C 15 VALVE SUBCODE A 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LER NO REPORT NUMBER 17 EVENT YEAR 8 2 21 22 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER P 0 2 5 26  
ACTION TAKEN B 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 32

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE CHECK VALVE WAS STICKING BECAUSE OF A BENT GUIDE FINGER. THE FINGER WHICH  
1 1 ACTS AS A GUIDE FOR THE BALL WAS STRAIGHTENED. THE CHECK VALVE, ITEM NO. T14  
1 2 ON PACIFIC PUMPS DRAWING NO. L0-45603, FUNCTIONED PROPERLY FOLLOWING REPAIR.  
1 3  
1 4

1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION OPERATOR OBSERVATION 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL EXPOSURES NUMBER 0 10 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PUBLICITY ISSUED DESCRIPTION N 44  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8205140472 820506  
PDR ADDOCK 05000316  
S PDR

NRC USE ONLY

NAME OF PREPARER DAVID G. WIZNER

PHONE 465-5901