

50-439

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

May 3, 1982

USNRC REGION II
ATLANTA, GEORGIA

82 MAY 6 4:39

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


BELLEFONTE NUCLEAR PLANT UNIT 2 - WELDING OF STRUCTURAL STEEL ANNULUS FLOOR
FRAMING - NCR 1173 - NINTH INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector R. W. Wright on April 15, 1980, in accordance with 10 CFR 50.55(e). This was followed by our interim reports dated May 15, July 30, and November 7, 1980, February 20, June 23, July 28, and October 26, 1981, and February 9, 1982. All of the 566 welds selected per MIL-Standard 105D have been reinspected. TVA is still reviewing the results of the reinspection of the subject welds. We expect to submit our next written report by June 9, 1982.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

8205180244 S

An Equal Opportunity Employer

IE 27
5/11